

# PRODUCT SAFETY RECALL



## Telwater Pty Ltd - Stacer Navigation Light Mounting Plate Sold at Stacer dealers & other boat retailers nationally

### PRODUCT DESCRIPTION:

Navigation light mounting plate situated within the bow rail and fitted to some Stacer boat models manufactured between 17 August 2005 and 6 February 2012. Refer to photo for style.

Not all boat models were affected.

A list of potentially affected boat HIN's is attached to the recall notice at [www.recalls.gov.au](http://www.recalls.gov.au) and the Stacer website [http://www.stacer.com.au/](http://www.stacer.com.au) for your reference.

### DEFECT:

In some circumstances it may be possible for a person's finger to be caught between the edge of the navigation light mounting plate and the bow rail tube.

### HAZARD:

If the defect occurs, the edge of the navigation light mounting plate may cause cuts or serious injury to the trapped finger.

### WHAT TO DO:

Consumers should immediately stop using the boat and check the style of navigation light mounting plate against the example picture.

For further information customers should contact their nearest Stacer dealer to arrange for inspection and rectification if necessary.

#### For further information

Please direct all calls and any queries concerning this recall to:

- your nearest Stacer dealer; or
- email: [recall@telwater.com.au](mailto:recall@telwater.com.au)

See [www.recalls.gov.au](http://www.recalls.gov.au) for Australian product recall information